

# Failure Analysis of 304 Stainless Steel Tubes of Intercooler Carbon Dioxide Compressor

Amir Arifin, *Member, IAENG*, Gunawan, Irsyadi Yani, and Hengki Irawan

**Abstract**—The annual inspection of the petrochemical plant revealed that SS 304 tubes at Intercooler CO<sub>2</sub> Compressor have failed. Some heat exchanger tubes were found during inspection with circumferential cracks. Some analysis methods were performed to investigate heat exchanger tube failures, such as X-Ray diffraction analysis, XRF (X-ray fluorescence) analysis, hardness test, morphology analysis, and numerical analysis. Investigation results revealed that pitting corrosion has been found on the inner surface of the tube that an essential factor in initiating cracks. Moreover, some porosities were observed spread distributed on the surface sample, which is believed to reduce the mechanical and physical value of the material. The corrosion and the fact that cracks were initiated in the relatively small tensile loads sites suggest that the component failure resulted from chloride-induced stress corrosion cracking. Investigation results for heat exchanger parameters, chloride content, and temperature operation have become the main factor in initiating chloride stress corrosion cracking (CSCC). The operational condition of the heat exchanger should not be referred to by the tube material austenitic SS 304. Regarding the systems with SS 304 tube heat exchangers and chloride content

**Index Terms**—SS 304, chloride stress corrosion cracking, heat exchanger tube, failure analysis.

## I. INTRODUCTION

Annual inspection is an essential procedure to ensure every piece of equipment works optimally, including equipment that works for heat exchange. Heat exchanger equipment is a system component that transfers heat from one medium to another effectively and efficiently. Fluids pass through distinct chambers, with the walls acting as a primary heat transfer surface. Secondary heat transfer surfaces, generally in the shape of corrugated metals known as fins within the flow chamber. Air, oil, water, and coolant are heat exchanger equipment most often utilize fluids.

Although this heat management unit has been commonly used, industries that use heat exchangers always face the problem of failure in their units. They are mostly related to

the temperature gradient, fouling, intergranular corrosion, and stress corrosion cracking (SCC) problems [2-5]. Stress corrosion cracking (SCC) is the cracking of a susceptible material produced by the presence of tensile stress and a corrosive medium simultaneously time. Interaction between environment and alloy composition on the cracking susceptibility of austenitic stainless steel in an aqueous chloride media has been the focus of considerable research [3].

A severe problem in the chemical and petrochemical sectors is the SCC of process equipment consisting 304 and 316 stainless steel caused by chlorides. Several cases of austenitic stainless steel process equipment and components failing due to chloride SCC have been reported, and various research has been performed to solve the issue [3, 6-11].

Some fertilizer plants have been shut down for six months. Galvanic corrosion on AISI type 304 Stainless steel intercooler and aftercooler become the main cause of failure [8]. In another failure case on Austenitic stainless steel, sensitization was found on AISI 304 stainless steel tube after five years of service at a working temperature of 500°C [12]. Another author reported the failure of 304 stainless steel tubes in a gas analyzer. Stress corrosion cracking results in several cracks on the tube surface that penetrate the inner tube [13]. In addition, the effect of the presence of NaOH and Chloride ions can reduce the mechanical properties of 304 stainless steel tubes [14].

This study aimed to investigate the cause of the failure of 304 stainless steel tubes of intercooler CO<sub>2</sub> compressor through metallurgical and mechanical tests and numerical analysis.

## II. EXPERIMENTAL PROCEDURES

Heat exchanger is one of vital equipment in petrochemical industry. Periodic checks are needed to maintain the performance of a heat exchanger.

An annual inspection of a petrochemical plant revealed that the Intercooler CO<sub>2</sub> Compressor's SS 304 tubes had failed. Clogged heat exchanger tubes will be due to a decrease in the performance of the heat exchanger. The circumferential crack position in the heat exchanger system can be shown in Figure 1. Around 94 tubes on the upper side were clogged with deposits, as shown in Figure 2. Commonly, clogged tubes are on the top tube of the heat exchanger.

Mechanical removal was conducted to clean the deposited material in Stainless steel 304 tubes. Furthermore, a leak test was conducted to investigate the tube leaks. One hundred forty-nine tubes were found in leaked condition after testing using compressed air at 7 kg/cm<sup>2</sup> on the middle area.

<sup>25</sup>Manuscript received February 07, 2022; revised November 10, 2022. This work was supported by Department of Mechanical Engineering, Sriwijaya University.

<sup>30</sup>Amir Arifin is an associate professor on Department of Mechanical Engineering, Sriwijaya University, 30662 Indralaya, South Sumatera, Indonesia (e-mail: amir@unsri.ac.id).

<sup>46</sup>Gunawan is a lecturer on Department of Mechanical Engineering, Sriwijaya University, 30662 Indralaya, South Sumatera, Indonesia. (Corresponding author to provide phone: +62-711-580-062; e-mail: gunawan@unsri.ac.id).

<sup>31</sup>Irsyadi Yani is a Head of Department on Mechanical Engineering, Sriwijaya University, 30662 Indralaya, South Sumatera, Indonesia. (e-mail: irsyadiyani@ft.unsri.ac.id).

Hengki Irawan is a senior engineer inspection on PT. Pupuk Sriwidjaja Palembang. 30118 Indonesia. (e-mail: hengki.irawan@pusri.co.id).




Fig. 1. Circumferential crack position in heat exchanger system.



Fig. 2. Deposits of material-clogged SS 304 tubes on the top side

Some tubes were removed from the bundle to analyze the leaking tubes. Visual observation shows that some circumferential cracks were observed on tubes. Furthermore, a dye penetrant test was carried out to investigate the tube's outer deeply. Circumferential cracks occur on the south tube sheet's 700–900 mm range. Moreover, the other tube sheet's 900 and 1200 mm from the south when pulled out.

X-ray diffraction analysis, XRF (X-ray fluorescence) analysis, hardness test, morphological analysis, and numerical analysis were all used to evaluate heat exchanger tube failures.

### III. RESULTS AND DISCUSSION

In this work, the analysis begins by analyzing the deposits contained in the SS 304 tubes. Deposit material composition in clogged pipes can be shown in Table 1. The main composition of the deposited material is silicon dioxide (31.88%). Based on the analysis results, the water used is believed to have been polluted by fly ash from the generator located near the heat exchanger system. The high content of SiO<sub>2</sub> evidences this. SiO<sub>2</sub> is the main constituent component of fly ash.

TABLE I.  
DEPOSITS MATERIAL COMPOSITION ON SS 304 TUBES

Element	C	Ni	Cr	Fe	SiO <sub>2</sub>	PO <sub>4</sub>
Wt%	9.1 %	0.48 %	0.06 %	18.2 %	31.88 %	2.49 %

Analysis of operational conditions on the tube exchange system was performed using numerical analysis to determine the heat exchanger tube temperature profile when operating.

A short simulation was performed to investigate the operating condition of the heat exchanger. Pressure and temperature were selected for input parameters due to having a significant contribution to failure. Figure 3 shows the analyzed heat exchanger model.




Fig. 3. Analyzed heat exchanger model

Figure 4. shows the numerical analysis result of the temperature gradient shell of the heat exchanger. Shell temperature increases significantly from the outlet heat exchanger. Moreover, the temperature gradient tube rises with increasing distance from the outlet, as shown in Figure 5.




Fig. 4. Temperature gradient shell side




Fig. 5. Temperature gradient tube side

Circumferential cracks positioned on the tube were found between 3480 to 3750 mm. Let's take the length of 3500 mm as a sample position. According to Figures 4 and 5, at the current position, the bulk temperature of the shell side is 155 °C, and the tube side is 37.7 °C. It is assumed that the heat transfer convection coefficient of water flowing in the tube is approximated at 500 to 1200 W/m<sup>2</sup>K and 10 to 350 W/m<sup>2</sup>K for gas flow between tubes. The temperature distribution inside the tube wall between 77.7 to 82.6 °C is seen in Figure 6.




Fig. 6. Temperature distribution inside tube wall




Fig. 7. Pressure Gradient shell side




Fig. 8. Pressure Gradient tube side

Figure 7 shows that the pressure increases with the length; at 3500 mm, the pressure was obtained at 8530 kPa. On the other hand, the pressure tube side decreases with the length, as shown in Figure 8. At a position of 3500 mm, a stress analysis is performed with the higher stress distribution located inside the tube wall, as shown in Figure 9.

Operational conditions play an essential role in triggering

the occurrent failure mode. Some factors affecting pitting corrosion include environmental and surface conditions, metal composition, and temperature, besides critical factors such as ion concentration and pH.




Fig. 9. Stress analysis tube side

In the austenitic stainless-steel case, some factors significantly determine failure modes, such as stress, temperature, chloride concentration, and pH. Figure 10 shows the effect of temperature parameters and chloride concentration for stress corrosion cracking.




Fig. 10. Effect temperature and chloride concentration for stress corrosion cracking stainless steels [18].

Table 2 shows the susceptibility to cracking chloride stress corrosion cracking, referring to the tube heat exchanger operation condition on 4. It can be categorized as very high conditions susceptible to forming chloride stress corrosion cracking.


In this case, chloride content in the water of the tube heat exchanger is around 44-68 ppm, and the maximum temperature operation is about 170°C, as shown in Table 3. Based on Figure 10, conclusions can be drawn that tube

43 hanger operation in the critical zone has passed the A Chloride stress corrosion cracking (CLSCC) thresholds of 304 stainless steels.

TABLE 2.  
SUSCEPTIBILITY TO CRACKING-CHLORIDE STRESS CORROSION CRACKING (CLSCC) [8].

Temperature (°C)	pH≤10			
	Susceptibility to Cracking as a Function of Chloride Ion (ppm)			
	1-10	11-100	101-1000	>1000
≤ 38	Low	Low	Low	Medium
>38 - 66	Low	Medium	Medium	High
>66-93	Medium	Medium	High	High
>93-149	Medium	High	High	High
>149	High	High	High	High
Temperature (°C)	pH>10			
	Susceptibility to Cracking as a Function of Chloride Ion (ppm)			
	0	11-100	101-1000	>1000
≤ 38	None	None	None	None
>38 - 93	Low	Low	Low	Low
>93-149	Low	Low	Low	Medium
>149	Medium	Medium	Medium	High

The main water pollutant that attacks stainless steel is chloride. Chloride breaks down the passive layer by dissolving chromium and allowing the combination of water with iron to produce the red oxide Fe<sub>2</sub>O<sub>3</sub>, often known as hematite. There seem to be two stages to the chemical process. The first includes the oxidation of iron following the dissolution of the passive layer. Furthermore, the second involves the dissolution of chromium by the chloride ion.



24 X-ray diffraction analysis is a common means to determine the structure and relative configuration of solid compounds in a certain way. XRD result of the tube material is shown in Figure 11. XRD analysis shows another peak in the tube material sample was not found. Regarding this result, the transformation phase is not occurring on tube material. In other words, the material does not experience a state where it can change its phases, such as high temperatures or mechanical processes.




Fig. 11. X-ray diffraction result for tubes material

The initial investigation of failure is to analyze the composition of the tube. XRF (X-ray fluorescence) was

utilized to analyze the composition of failure tubes. XRF results as shown in Table 3. Based on the XRF result, the tubes that have the second major element after Fe are Cr and Ni for 18.49 % and 8.06 %, respectively, according to SS 304

TABLE 3.  
COMPOSITION OF FAILURE TUBE

Element	Cr	Fe	Ni	Cu	Mo
Content	18.49	72.11	8.06	0.333	0.114

Hardness measurement for SS 304 using the Vickers method at the tube cross-section. The hardness measurement result shows no significant difference in hardness value compared to the ASM Material Data Sheet for SS 304, as shown in Table 4.

TABLE 4.  
HARDNESS RESULT USING VICKERS METHOD

No	VHN	Remark
1.	189	ASM Material Data Sheet
2.	198.4	Measurement results
	180.2	
	188.9	185.6
	174.8	




Fig. 12. Microstructure of austenitic stainless steel 304 tube

Morphology observation was carried out utilizing by the digital microscope and optical microscope. Figure 12 revealed an austenite structure, characterized as austenitic stainless steel 304.




Fig. 13. Microstructure of austenitic stainless steel 304 with some porosity on the surface.

Moreover, porosities and pitting corrosion were evenly

distributed on the surface sample, as shown in Figures 12 and 13. The occurrence of porosity was believed to be due to manufacturing results. On the other hand, pitting corrosion occurs due to unsuitable conditions for SS 304.

Figure 14 show some cracks found on the tube's inner surface, which were believed to be stress corrosion cracking. All of the cracking has a similar pattern (circumferential crack).




Fig. 14. Inner surface morphology of tube

In the shutdown period, CLSCC can appear when a solution contains chlorides, especially at temperatures above 60 °C. In general, CLSCC has a transgranular formation and many branches. Stainless steel is very susceptible to CLSCC of Austenitic type with a nickel content of 8%, such as Type 300 series, stainless steel 304, and 316. Lower or higher nickel content alloys generally indicate the resistance of stainless steel to higher CLSCC. The CLSCC commonly does not influence duplex stainless steels with a low nickel content like it does alloys with nickel content above 42%.

If the required electrochemical, mechanical, and metallurgical conditions are fulfilled, cracks may initiate already-existing surface flaws, or corrosion processes may generate a surface imperfection through pitting or localized corrosion. Pits, manufacturing defects, and intergranular corrosion, which all contribute to SCC start, are visible and identifiable, as demonstrated in Figure 15 pitting corrosion in an inner tube.




Fig. 15. Cracks start from corrosion pits.

Pitting corrosion is critical in initiating failure, especially under complex conditions such as pressure and temperature. In this case, some cracks were found in the inner surface of the tube. Crack initiation and propagation are different but highly related processes; when the crack has been initiated, it propagates.

Austenitic stainless-steel components are susceptible to pitting and crevice corrosion in wet, humid environments containing chloride ions. Components with residual stress may crack due to stress corrosion under these conditions. A vessel or piece of equipment may become perforated due to pitting, simply the breakdown of the chromium oxide layer followed by localized corrosion that results in pits. Instead of the macroscopic physical characteristics of a component, pitting is mostly related to the microscopic heterogeneities of a surface. Localized corrosion is followed by breaking the chromium oxide layer in crevices. However, unlike pitting, it only occurs at specific physical features when a partially shielded surface and a stagnant solution are present at the covered area's interface.




Fig. 16. SEM micrographs of Chloride stress corrosion cracking.

Figure 16 shows SEM analysis of the crack on the inner surface of the tube. Morphology analysis for the cracks revealed that the fracture surface is characterized as transgranular fracture, which is the crack propagation along grain boundaries.

In SCC- and stress-dominated regions, transgranular cracking exhibited greater elongation rate and higher failure times. In contrast, the failure in intergranular cracking was gradual and frequently occurred in the steady-state elongation area, indicating a minimum of mechanical elongation prior to failure. Intergranular cracking for these austenitic stainless steels consequently showed a more brittle than transgranular cracking.

Transgranular cracking, on the other hand, is unrelated to martensite generated at grain boundaries and is brought on by the growth of fractures initiated at slip steps. Thus, transgranular cracking like this is considered stress corrosion cracking (SCC) in the strict definition of the term.

At lower temperatures, Type 304 experienced intergranular cracking, and at higher temperatures transgranular cracking. The formation of martensite and the

competition between the material's dissolution at slip stages, which induces SCC, and hydrogen entry, which causes HE, determines the cracking mode. The difference between hydrogen absorption and hydrogen escape determines the hydrogen entry. For type 304, transgranular SCC was generated by spreading fractures that started at slip steps rather than martensite grain boundaries. The cracking mode would thus be determined by the competition between the dissolving rate at slip stages and the hydrogen entry rate at grain boundaries with martensite.

According to a commonly understood literature review, the time to failure in samples subjected to SCC reduces as the applied tensile stress increases [15-17]. According to data, increased applied tensile stress does not result in accelerated fracture propagation or higher crack density. Since stress is thought to play a crucial role in breaking the oxide coating that shields the bare metal, higher applied tensile stress should increase fracture density and a shorter time to failure.

Environmental cracking of 300 Series SS and various nickel-based alloys under stress, temperature, and an aqueous chloride environment promotes surface-initiated cracks. The presence of dissolved oxygen increases the potential to crack [18].

#### IV. CONCLUSION

The investigation has been conducted to analyze the failure of SS 304 tubes at the Intercooler CO2 Compressor. Some significant results can be concluded. Based on analysis using XRF (X-ray fluorescence), X-Ray diffraction analysis, and hardness measurement, tube heat exchanger material is according to SS 304.

Visual observations reveal that pitting corrosion has been found on the tube's inner surface, an essential factor in initiating cracks. Moreover, porosities were observed to spread and distribute on the sample surface, which is believed to reduce the mechanical and physical value of the material. Cracks start from the tube's inner surface to the outer surface in the circumferential direction.

The presence of corrosion and the fact that cracks developed in the areas of relatively light tensile loads imply that the component failed as a result of chloride-induced stress corrosion cracking. Investigation results for heat exchanger parameters, chloride content, and temperature operation have become the main factor in initiating chloride stress corrosion cracking (CSCC). The operational condition of the heat exchanger should not be referred to by the tube material austenitic SS 304. According to the heat exchanger system's operating temperature and chloride concentration.

#### REFERENCES

- [1] Abdulaziz A. Bubshait, and Alawi Basurrah, "Impact of Reliability Centered Maintenance on Equipment Availability and Cost Optimization," Lecture Notes in Engineering and Computer Science: Proceedings of The World Congress on Engineering 2019, 3-5 July, 2019, London, U.K., pp.345-350.
- [2] X. Yang, M. Liu, Z. Liu, C. Du, and X. Li, "Failure analysis of a 304 stainless steel heat exchanger in liquid sulfur recovery units," *Engineering Failure Analysis*, vol. 116, 2020.
- [3] K. Ravindranath and R. Alazemi, "Failure of stainless steel 304L air cooler tubes due to stress corrosion cracking caused by organic chlorides," *Engineering Failure Analysis*, vol. 102, pp. 79-86, 2019.

- [4] A. Arifin, Gunawan, and I. Yani, "Failure analysis of AISI 304 stainless steel pipeline transmission a petrochemical plant," *IOP Conference Series: Materials Science and Engineering*, vol. 857, no. 1, 2020.
- [5] P. R. Roberge, *Corrosion Basics: An Introduction*. NACE International, 2006.
- [6] S. M. R. Ziaei, J. Mostowfi, M. Golestani pour, and S. A. R. Ziaei, "Failure analysis: Chloride stress corrosion cracking of AISI 316 stainless steel downhole pressure memory gauge cover," *Engineering Failure Analysis*, vol. 33, pp. 465-472, 2013.
- [7] R. Nishimura, A. Sulaiman, and Y. Maeda, "Stress corrosion cracking susceptibility of sensitized type 316 stainless steel in sulphuric acid solution," *Corrosion Science*, vol. 45, no. 2, pp. 465-484, 2003.
- [8] H. Shaikh, R. V. Subba Rao, R. P. George, T. Anita, and H. S. Khatak, "Corrosion failures of AISI type 304 stainless steel in a fertilizer plant," *Engineering Failure Analysis*, vol. 10, no. 3, pp. 329-339, 2003.
- [9] W. Tian, S. Li, N. Du, S. Chen, and Q. Wu, "Effects of applied potential on stable pitting of 304 stainless steel," *Corrosion Science*, vol. 91, pp. 242-255, 2015.
- [10] S. K. Pradhan, P. Bhuyan, and S. Mandal, "Influence of the individual microstructural features on pitting corrosion in type 304 austenitic stainless steel," *Corrosion Science*, vol. 158, 2019.
- [11] M. Ali, A. Ul-Hamid, L. M. Alhems, and A. Saeed, "Review of common failures in heat exchangers – Part I: Mechanical and elevated temperature failures," *Engineering Failure Analysis*, vol. 109, 2020.
- [12] A. Bahrami and P. Taheri, "A Study on the Failure of AISI 304 Stainless Steel Tubes in a Gas Heater Unit," *Metals*, vol. 9, no. 9, 2019.
- [13] Y. Li *et al.*, "Failure analysis of the 304 stainless steel tube in a gas analyzer," *Engineering Failure Analysis*, vol. 20, pp. 35-42, 2012.
- [14] M. R. Jahangiri, "Failure Analysis of Type 304 Stainless Steel Tubes in an Energy Production Plant Heat Exchangers," *Journal of Pressure Vessel Technology*, vol. 133, no. 6, 2011.
- [15] Z. Que, T. Saario, A. Toivonen, and U. Ehmstén, "Stress corrosion cracking initiation susceptibility of Alloy 182 with different surface treatments," *Corrosion Science*, vol. 196, 2022.
- [16] X. Chen, E. Karasz, N. Badwe, and K. Sieradzki, "Dynamic fracture and dealloying induced stress-corrosion cracking," *Corrosion Science*, vol. 189, 2021.
- [17] T. M. Ahn, "Long-term initiation time for stress-corrosion cracking of alloy 600 with implications in stainless steel: Review and analysis for nuclear application," *Progress in Nuclear Energy*, vol. 137, 2021.
- [18] A. P. Institute, *Risk-based Inspection Methodology: API Recommended Practice 581*. 2016.



**Amir Arifin** is an Associate Professor in the Department of Mechanical Engineering at Sriwijaya University and an IAENG member. His research interest includes biomaterials, welding, powder metallurgy, and casting. He has publications in Materials & Design, PloS one, Journal of Mechanical Engineering & Sciences, International Journal of Technology, Journal of Engineering Science and Technology, Materials Research Innovations, Lecture Notes in Mechanical Engineering, and IOP Conference Series.



**Gunawan** is currently a lecturer in the Department of Mechanical Engineering at Sriwijaya University. His research interest includes Biomaterials, welding, powder metallurgy, and casting. He has publications in Materials and Manufacturing Processes, Recent Patents on Materials Science, Key Engineering Materials, Journal of Physics, Advances in Environmental Science and Technology, Lecture Notes in Mechanical Engineering, and the IOP Conference Series.



**Irsyadi Yani** is head of the Department of Mechanical Engineering at Sriwijaya University. His research interest includes Intelligent Systems and Numerical Analysis. He has published in: the Journal of Mechanical Engineering and Sciences, the Journal of Physics, the Indonesian Journal of Electrical Engineering and Computer Science, the Journal of Multidisciplinary Engineering Science and Technology, the European Journal of Scientific Research, Lecture Notes in Mechanical Engineering, and the IOP Conference Series.



**Hengki Irawan** is Senior Engineer Inspection in PT. Pupuk Sriwidjaja, South Sumatera, Indonesia. He is an expert in welding inspection and risk-base **25** inspection for a fertilizer plant. B.Eng (2007) in Department of Mechanical engineering, **6** Sriwijaya University-Indonesia. M.Eng. (2015) in Department of Materials and Metallurgical Engineering, Institut Teknologi Sepuluh Nopember - Indonesia

## ORIGINALITY REPORT

**27%**  
SIMILARITY INDEX

**19%**  
INTERNET SOURCES

**22%**  
PUBLICATIONS

**8%**  
STUDENT PAPERS

## PRIMARY SOURCES

<b>1</b>	<a href="http://mycommittees.api.org">mycommittees.api.org</a> Internet Source	<b>2%</b>
<b>2</b>	<a href="http://www.hindawi.com">www.hindawi.com</a> Internet Source	<b>2%</b>
<b>3</b>	R. Haque, H. Fairweather, A. Olofinjana. "Failure Analysis of Boat Rudder Fitting Fabricated from a Type 304 Stainless Steel", Journal of Failure Analysis and Prevention, 2018 Publication	<b>1%</b>
<b>4</b>	<a href="http://www.iaeng.org">www.iaeng.org</a> Internet Source	<b>1%</b>
<b>5</b>	O. M. Alyousif, R. Nishimura. "On the SCC behaviour of austenitic stainless steels in boiling saturated magnesium chloride solution", Simulation of Electrochemical Processes II, 2007 Publication	<b>1%</b>
<b>6</b>	<a href="http://iptek.its.ac.id">iptek.its.ac.id</a> Internet Source	<b>1%</b>



7	<a href="http://journal.ump.edu.my">journal.ump.edu.my</a> Internet Source	1 %
8	K. Ravindranath, R. Alazemi. "Failure of stainless steel 304L air cooler tubes due to stress corrosion cracking caused by organic chlorides", Engineering Failure Analysis, 2019 Publication	1 %
9	<a href="http://data.mendeley.com">data.mendeley.com</a> Internet Source	1 %
10	<a href="http://www.researchgate.net">www.researchgate.net</a> Internet Source	1 %
11	<a href="http://vbook.pub">vbook.pub</a> Internet Source	1 %
12	<a href="http://yetl.yabesh.ir">yetl.yabesh.ir</a> Internet Source	1 %
13	<a href="http://downloads.hindawi.com">downloads.hindawi.com</a> Internet Source	1 %
14	Addepalli, Sri, David Eiroa, Suphansa Lieotrakool, Anne-Laure François, Juliette Guisset, David Sanjaime, Michele Kazarian, Julia Duda, Rajkumar Roy, and Paul Phillips. "Degradation Study of Heat Exchangers", Procedia CIRP, 2015. Publication	1 %
15	Submitted to National University of Singapore Student Paper	1 %

16	<a href="http://corrosionjournal.org">corrosionjournal.org</a> Internet Source	1 %
17	<a href="http://cris.vtt.fi">cris.vtt.fi</a> Internet Source	1 %
18	<a href="http://www.engineeringletters.com">www.engineeringletters.com</a> Internet Source	1 %
19	Osama M. Alyousif, Rokuro Nishimura. "The stress corrosion cracking behavior of austenitic stainless steels in boiling magnesium chloride solutions", Corrosion Science, 2007 Publication	1 %
20	<a href="http://publisher.uthm.edu.my">publisher.uthm.edu.my</a> Internet Source	1 %
21	Submitted to Taylor's Education Group Student Paper	1 %
22	<a href="http://studi.ristekdikti.go.id">studi.ristekdikti.go.id</a> Internet Source	1 %
23	Chi Wang, Bin Kuang, Zhuli Wen, Jianmei Sun, Yewen Xu, Anand Asundi. "Further study of coupling efficiency of ultra-small gradient-index fiber probe", Optik, 2019 Publication	<1 %
24	<a href="http://epdf.pub">epdf.pub</a> Internet Source	<1 %

- |    |   |      |
|----|---|------|
| 25 | Hendri Chandra, Diah Kusuma Pratiwi, Muhammad Zahir. "High-temperature quality of accelerated spheroidization on SUP9 leaf spring to enhance machinability", Heliyon, 2018<br>Publication                           | <1 % |
| 26 | Submitted to University of Queensland<br>Student Paper  | <1 % |
| 27 | Submitted to University of Strathclyde<br>Student Paper   | <1 % |
| 28 | <a href="http://aca-a-usa.org">aca-a-usa.org</a><br>Internet Source   | <1 % |
| 29 | <a href="http://home.iitk.ac.in">home.iitk.ac.in</a><br>Internet Source   | <1 % |
| 30 | "Human-Centered Technology for a Better Tomorrow", Springer Science and Business Media LLC, 2022<br>Publication   | <1 % |
| 31 | E P Riyanto, I Yani, A Arifin, M Zahir. "Design Optimization in Stress Distribution of Firing Pin Rifle by Impact Force Using Finite Element Modelling", Journal of Physics: Conference Series, 2019<br>Publication | <1 % |
| 32 | Jin-hui Zhai, Bei-bei Sun, Yang Zhou. "Failure analysis on 304 stainless steel tube of semi   | <1 % |

# water gas preheater in coal chemical plant", Engineering Failure Analysis, 2021

Publication

33

[www.10wenku.com](http://www.10wenku.com)

Internet Source

<1 %

34

[d-nb.info](http://d-nb.info)

Internet Source

<1 %

35

[section.iaesonline.com](http://section.iaesonline.com)

Internet Source

<1 %

36

B.S.C. Rao, R. Madeswaran, R. Chandramohan. "In-fabrication and pre-service care on stainless steel pressure vessels", International Journal of Pressure Vessels and Piping, 1997

Publication

<1 %

37

Daochen Feng, Zhengyang Li, Wenjian Zheng, Zhou Zhou, Guoben Gao, Jianguo Yang, Zengliang Gao. "Failure analysis of welded joint leakage of TP321 pressure pipeline", Engineering Failure Analysis, 2022

Publication

<1 %

38

[coek.info](http://coek.info)

Internet Source

<1 %

39

[link.springer.com](http://link.springer.com)

Internet Source

<1 %

40

Jin-hui Zhai, Bei-bei Sun. "Fracture Analysis of Stress Corrosion Cracking in Heat Exchanger Tubes", 2021 3rd International Conference on Intelligent Control, Measurement and Signal Processing and Intelligent Oil Field (ICMSP), 2021

Publication

---

<1 %

41

Osama M. Alyousif, Rokuro Nishimura. "On the Stress Corrosion Cracking and Hydrogen Embrittlement Behavior of Austenitic Stainless Steels in Boiling Saturated Magnesium Chloride Solutions", International Journal of Corrosion, 2012

Publication

---

<1 %

42

S. W. Liu, W. Z. Wang, C. J. Liu, J. B. Huang, L. P. Guan. "Failure Analysis of the Tubes in a Methanol Synthesis Tower", Journal of Failure Analysis and Prevention, 2019

Publication

---

<1 %

43

Samir Milad Elsariti, Haftirman. "Behaviour of Stress Corrosion Cracking of Austenitic Stainless Steels in Sodium Chloride Solutions", Procedia Engineering, 2013

Publication

---

<1 %

44

Suwarno Suwarno, Abdul Jabar I'jazurrohman, Fajar Dwi Yudanto, Vivien S. Djanali. "Failure analysis of waste heat boiler tubing caused by

<1 %

# a high local heat flux", Engineering Failure Analysis, 2022

Publication

45

Xiuyun Wang, Lijie Qiao, Lei Zhang. "Analysis of the Causes of the Cracking of Tube Bundles of 316L Stainless Steel Shell-and-Tube Heat Exchanger", Engineering Failure Analysis, 2022

Publication

<1 %

46

[journalarticle.ukm.my](http://journalarticle.ukm.my)

Internet Source

<1 %

47

[researchspace.ukzn.ac.za](http://researchspace.ukzn.ac.za)

Internet Source

<1 %

48

[www.irantpm.ir](http://www.irantpm.ir)

Internet Source

<1 %

49

Xu, Na, Jun Bo Shi, Yong De Li, Wei Min Guo, Xiao Feng Wu, Shu Xin Han, Qi Shan Zang, and Zhi Wen Hu. "Failure Analysis of Water-Wall Tubes in the High-Pressure Boiler", Advanced Materials Research, 2014.

Publication

<1 %

50

Yao Wang, Tianxiang Li, Jing Zhu. "Study on treatment of wastewater with low concentration of ammonia nitrogen by vacuum plate membrane distillation technology", Water Science and Technology, 2022

Publication

<1 %

51

Murad Ali, Anwar Ul-Hamid, Luai M. Alhems, Aamer Saeed. "Review of common failures in heat exchangers – Part I: Mechanical and elevated temperature failures", Engineering Failure Analysis, 2020

Publication

---

<1 %

52

S.H. Khodamorad, N. Alinezhad, D. Haghshenas Fatmehsari, K. Ghahtan. "Stress corrosion cracking in Type.316 plates of a heat exchanger", Case Studies in Engineering Failure Analysis, 2016

Publication

---

<1 %

---

Exclude quotes Off

Exclude matches Off

Exclude bibliography Off